

Technical Bulletin

Bulletin Number: 430 Revision Number: R-00

Release Date: April 2, 1992 Revision Date: _____

SUBJECT: CAN / BOTTLE DELIVERY CHUTE ADJUSTMENT

MODELS AFFECTED: Model 276 Venders Serialized 0001-6000 to 0001-6066

REASON: Adjustment is needed if cans in the #1 column (T-handle side of vender) lie between the top right edge of the can / bottle chute and the inside vender wall. This is caused by can / bottle chute movement during shipping.

TO CORRECT POTENTIAL PROBLEM:

1. Ensure vender is level.
2. Loosen two front mounting screws that secure can / bottle chute to mullion.

WARNING: LOOSEN ONLY; DO NOT REMOVE SCREWS. IF SCREWS ARE REMOVED THE CAN / BOTTLE CHUTE MAY FALL FROM VENDER.

3. Center can / bottle chute in vender so that the top back edges are approximately the same distance from the outside column walls of the stack assembly.
4. Raise the front of the chute to the maximum height allowed by the two slots in the chute mounting plate and secure.
5. Secure by tightening two screws.

NOTE: DO NOT OVER TIGHTEN SCREWS.