Dixie-Narco



Lawrence Street Ranson, West Virginia 25438

(304) 725-3481 33 (800) 624-0553

Service Bulletin

Date: October 8, 1987 Revised: September 18, 1989

MODELS: All INCB Venders with Curved Sign Face

SUBJECT: First Change - 1/2" Radii added to Lexan at discharge port.

REASON: In an attempt to reduce the sign face "splits", a 1/2" radius

has been added to each corner in the Lexan Sign in the discharge

🖁 port area.

BIGINNING SERIAL NUMBER: 0001-2988CL

MODELS: All DNCB Venders with Curved Sign Face

SUBJECT: Second Change - Delivery Port

REASON: To further reduce sign face splits, the delivery port was shortened i.e.,

no longer against sign face.

BEGINNING SERIAL NUMBER: 0001-3026

MODELS: All DNCB Venders with Curved Sign Face

SUBJECT: Third Change - Top of Port Trim

REASON: To further reduce sign face splits, a fluid silastic material was inserted

between top port trim and front of lexan panel.

BEGINNING SERIAL NUMBER: 0001-3113BN