

Technical Bulletin


Bulletin Number: 407 Revision Number: R-01

Release Date: January 17, 1990 Revision Date: June 9, 1993

SUBJECT: Adjustable Brown Cam for Narrow Column Vend Motor Part #B801,806,610.21

MODELS: All Series 90 Venders with Narrow Columns

REASON: The bottom of hole #2 was blocked off with a .010" wall thickness. This will prevent anyone from using this setting unintentionally. To use hole #2 it will be necessary to punch through it using the lobe on the bottom cam. This change went into effect in December 1990.



**Adjustable Brown Cam
801,806,610.21**