

Technical Bulletin

Bulletin Number: 315 Revision Number: R-02

Release Date: February 5, 1987 Revision Date: January 13, 2000

SUBJECT: Coin Reject Arm and Plunger Slide For Early Coke Landscape venders.

MODELS: DNCB Coke Venders Only serialized 0001-2949DK to 0001-2996CL.

REASON: To provide a solution to prevent the Coin Reject Arm from binding thus resulting at times in an inoperative vender.

BEGINNING SERIAL NUMBER:

1. 0001-2971 - Started to Factory install "Plunger Slides".
2. 0001-2979 - Started to Factory install "Plunger Slides" and Reject Arms.

- DO THIS:**
- a. Remove reject arm and replace with joggled reject arm provided.
 - b. Install plunger slide as shown. Remove washer from screw A. Leave it off.
 - c. Remove spring end from retainer.
 - d. Attach this spring end under screw head at A in slotted area. Make sure this screw is tight.

IMPORTANT:

1. Install Plunger Slide on all DNCB Coke Landscape Venders that do not have the plunger slide.
2. When using a Mars Coin Changer install both the Plunger Slide and the Reject Arm on all DNCB Coke Landscape Venders that do not have the plunger slide and the reject arm.

ORDER AS: 1 432,050,52x.x3 Plunger Slide
1 801,303,68x.x1 Reject Arm (Joggled)

