(304) 725-3481 (800) 624-0553

Lawrence Street Ranson, West Virginia 25438

## Service Bulletin #Date: 222

Dual Adaptable Red Cam.

To make everyone aware of parts which are used on Dual Adaptables that REASON:

are different from those used on Adaptable Red Cam.

## THE FOLLOWING ARE PARTS THAT ARE DIFFERENT ON DUAL ADAPTABLE RED CAM VENDERS.

804,200,190.01	Vend Sequencer - located on bracket on Inner Door adjacent to coin changer socket. Not used on all Dual Adaptables.
C231,070,400.03	Vend Motor Assembly for narrow column.
D801,200,980.21	Vend Rotor - located in narrow column.
B231,070,230.03	Can Shim - narrow column.
804,100,500.01	Switch Cluster (3) for Vend Motors.
804,100,490.01	Switch Cluster, Sold Out (2)
801,804,370.01	Large Button, 5 $1/4 \times 5 5/8$ , Not used on all Dual Adaptables.
	Wiring Harness - Select Panel, Order by Model #.
	Wiring Harness - Cabinet and Door, Order by Model #.