Dixie-Narco



Lawrence Street Ranson, West Virginia 25438 (304) 725-3481 (800) 624-0553

Service Bulletin

Date: June 18, 1984

270

MODELS: DNCB Venders 1 1/4" Deeper

SUBJECT: Vend Rotor - with rear can retainer

For Narrow Column Only

REASON: To provide a feature that will retain the rear can if the vender

is tilted.

ORDER AS: Part #D801,201,000.51 - Vend Rotor

BEGINNING SERIAL NUMBER: --- 2722-Part of the production run

0001-2730-Complete production run and thereafter

When a vend rotor is ordered for a 1 1/4" deeper vender the rotor described hereon will be shipped as a replacement.

On $1 \frac{1}{4}$ deeper venders from which cans are being free vended from the narrow column as a result of tilting (the vender) and the vend rotor is not the rotor with the "rear can retainer", order:

B3050.06 W/A Can Retainer Shim - 1 per Narrow Column (Reference - Service Bulletin #233)




Fig. 1