

Technical Bulletin

Bulletin Number: 327 Revision Number: R-02

Release Date: October 1, 1987 Revision Date: January 4, 1999

SUBJECT: END CAP, TRIM

MODELS AFFECTED: DNCB 180CC (Landscape) Venders
All DNCB Seven-Up B7 Venders

REASON: To close the end caps for cosmetic purposes.

ORDER: 903,600,48x.x1 Black Sealant


Install sealant in top of trim to prevent water from entering and to improve the cosmetic appearance of the trim.

For a short period of time beginning 0001-6093CQ Trim Caps were used. This was discontinued due to cosmetic problems.




Top View

Trim Cap
1 per 180 Coke CC
801,807,09x.x1
OBSOLETE



Side View of
Both Parts



Top View

Rim Cap
1 per 180 Coke CC and
7UP B7
801,807,08x.x1
OBSOLETE

SERIAL BREAK: Beginning serial number 0001-6093CQ (Sept. 1992)

Usage: For Coca-Cola 180CC Landscape Venders use one (1) each of 801,807,09x.x1 (OBSOLETE) and 801,807,08x.x1 (OBSOLETE).
For all 7UP B7 Venders use one (1) of 801,807,08x.x1 (OBSOLETE).

The new parts listed above replace part numbers:

801,805,86x.x1 Trim cap now obsolete.
801,805,87x.x1 Trim cap now obsolete.

(Old parts were installed on Coca-Cola 180CC models productions 0001-3025DL to 0001-6093CQ and 7UP B7 0001-3040 to 0001-6093CQ.)