

Technical Bulletin

Bulletin Number: 378 Revision Number: R-02

Release Date: April 26, 1989 Revision Date: August 7, 1998

SUBJECT: **TEFLON COATED THREADSTUDS ($\frac{1}{2}$ " $\frac{7}{8}$ ", AND 1")**
Subject Studs Are Being Coated With Teflon Prior To Application Of Paint

MODELS AFFECTED: All Dixie-Narco Venders.

BEGINNING SERIAL NUMBER: 0001-3118BN and higher;
Except production runs 3124, 3125, and 3126.

REASON: To ease keps nut installation and prevent paint adherence to threads which resulted in nut lock-up.

<u>PART NUMBERS AFFECTED:</u>	901,001,07x.x1	Threadstud, Coated #8-32x $\frac{1}{2}$ "
	901,001,14x.x1	Threadstud, Coated #8-32x $\frac{7}{8}$ "
	901,001,22x.x1	Threadstud, Coated #8-32x1"