

Technical Bulletin

Bulletin Number: 390 Revision Number: R-01

Release Date: September 14, 1989 Revision Date: August 7, 1998

OBSOLETE

Please Contact:
Ardac, Inc.
34000 Vokes Drive
Eastlake, OH 44095
Ph: 216-946,3000
Fax: 216-942-1835

SUBJECT: **BOTTOM BILL ENTRANCE**
(Ranson Inventory Replacement)

MODEL: ARDAC USA-15

REASON: To install the revised Bottom Bill Entrance which has a black belt retainer on either side. This replacement part is designed to prevent the Black Belt from coming off the roller.

IDENTIFICATION: The serial number range of the USA-15's being updated is 059, 069, and 079.

Updating started on September 7, 1989.

These updated USA-15's have an identity mark on the very top of the validator as:

1. White pressure sensitive disc OR
2. The figure 1 OR
3. The figure 2 OR
4. The figure 3.

The white disc was used on 200 to 300 of the updated validators and then discontinued in favor of shift #'s, i.e. 1 or 2 or 3.



Bottom Bill Entrance

ARDAC PRODUCTION
MODEL USA-15:

Beginning with s/n 089 a revised Bottom Bill Entrance was installed as the USA-15 was produced.