

Technical Bulletin

Bulletin Number: 429 Revision Number: R-02

Release Date: January 22, 1992 Revision Date: March 26, 1993

SUBJECT: NEW 12oz. CAN STOP SHIM FOR "T" MODEL VENDERS NARROW COLUMNS.
NEW PART NUMBER B497,070,130.83

MODELS: 501T SERIES 90 501T MPC
600T SERIES 90 600T MPC


REASON:

- A. The can retention is increased for the second can (middle) in a narrow column.
- B. The shim prevents the potential for an early delivery of the second can (middle) in a narrow column.

BEGINNING SERIAL NUMBER: "T" Model venders beginning serial number 0001-6096CQ and up will have the shim factory installed.

TO INSTALL NEW SHIM:

1. Remove existing can stop shim.



2. Install new can stop shim (497,070,130.83).

