

Technical Bulletin

Bulletin Number: 435 Revision Number: R-01

Release Date: September 10, 1992 Revision Date: October 26, 1992

SUBJECT: IMPROVED CONDENSER COATING

MODELS AFFECTED: All.

REASON: To improve the condenser's ability to combat the harsh elements it is exposed to in the field, therefore giving it a greater life span.

Note: New condensers are referred to as new "E" Coat Condenser Coils.

All LTC's with the new coating will have the label below applied to them.



903,833,480.01

SERIAL BREAKS:

Vender Models Affected:	Compressor Identification	Compressor Part #	Beginning Production Run New "E" Coat is factory installed.	Beginning Service Refrigeration Units that new "E" Coat is factory installed.
168, 180, 276, 300	1/4HP	802,600,560.01	6085CQ and Up	0001-1077CQ & Up
348, 360, 368, 414, 432, 440	1/3HP	802,600,550.01	6080BQ and Up	0588-1059BQ & Up
501, 522, 600	S1/3HP	802,600,540.01	6077BQ and Up	0084-1074BQ & Up