

Technical Bulletin

Bulletin Number: 480 Revision Number: R-01

Release Date: November 1, 1993 Revision Date: July 23, 1998

SUBJECT: COIN OPENING FILLER PLATE


MODELS AFFECTED: All Landscape Coke Non-VRV Venders and All Ranson Built Redesigned Magnum Circular Venders.

SERIAL NUMBER BREAKS:

- A) Landscape Coke Non-VRV Venders serialized 0001-2949DK to 0001-6123BR.
- B) All Ranson Built Redesigned Magnum Circular Venders serialized 0001-3101AN to 0001-3233CP.

REASON: To provide a part that blocks the coin opening of the coin insert to prevent coins from being used.

ORDER: 480,050,07x.x3 Coin Opening Filler Plate



TO INSTALL:

1. Remove existing coin insert retainer.
2. Install coin opening filler plate in its place.