

Technical Bulletin

Bulletin Number: 492 Revision Number: R-01


Release Date: June 21, 1995 Revision Date: July 23, 1998

SUBJECT: SII CONTROL BOX BUTTON COVER

MODELS AFFECTED: All SII Venders.

SERIAL BREAK: All SII Venders Serialized 0001-6111AR to 0773-6201CS.
Includes production run 6204.

REASON: To provide a cover to limit access to the set-up/audit and diagnostic buttons on the SII control box.



572,010,040.03

ORDER: 572,010,040.03 Button Cover, SII Box

TO INSTALL:

1. Locate the bottom right screw that secures the SII control box to the vender.
2. Loosen the screw.
3. Place the button cover in position over the set-up/audit and diagnostics button, so the slot in the cover goes under the screw you loosened in step 2.
4. Tighten the screw to secure the button cover in place.