


Technical Bulletin



**TOMORROW'S
MANUFACTURING
LEADERSHIP
TODAY**


Bulletin Number: 495 Revision Number: _____
Release Date: Oct. 11, 1995 Revision Date: _____

SUBJECT: VENTED HOLE PLUG FOR T-MODELS

MODELS AFFECTED: All T-models with 2" air holes in the can/bottle chute.

SERIAL BREAK: 0001-6000CO and higher.

REASON: To provide a part that eliminates certain packages from standing in the 2" vent holes of T-model can/bottle chutes.



ORDER: 800,101,780.01 2" Vented Hole Plug (Heyco 2786)

To Install:

1. Determine the hole in the can/bottle chute in which the package stand-up is occurring.
2. Push the plug down through the top of the can/bottle chute hole.

IMPORTANT

Only install the plug in the hole where the package stand-up occurs