

Technical Bulletin


Bulletin Number: 508 Revision Number: _____

Release Date: June 3, 1998 Revision Date: _____


SUBJECT: **EVAPORATOR FAN LEAD ADAPTER**

MODELS AFFECTED: All venders serialized 0001-6453 & higher.
Exceptions: Production runs 6454, 6456, 6457, 6466, 6475, and 6478


REASON: To provide adapter lead to allow old evaporator fan motors with a white amp housing to connect to the revised main wiring harness (804,902,22x.x1) which has a white Etco housing.




Evaporator Fan Lead Adapter
804,913,64x.x1
Figure 1




Lyall Tab on Main Wire
Harness
Figure 2



Etco Housing on
804,902,22x.x1
Main Wire Harness
Figure 3



Amp Receptacle on
Current Evaporator Leads
Figure 4



Old Amp Housing Receptacle
on Older Evaporator Fan
Motor Leads
Figure 5

The Evaporator Fan Lead Adapter (804,913,64x.x1) is needed in the field when an older Evaporator Fan Motor with an Amp Housing (figure 5) is being installed in a new vender with an Etco Housing (Figure 4) on the main wiring harness (804,902,22x.x1).