



CRANE National Vendors

SERVICE BULLETIN


12955 Enterprise Way
Bridgeton, MO 63044-1200

Technical Service (800) NAT-VEND
Parts (800) NA1-PART
Sales/Parts Fax (800) 531-2580
General Information (800) 325-8811

B6339902

September 8, 1999

Service spray hose assemblies part # 623-8071 and 485-8022 have been obsoleted and replaced by part # 633-8061 and 485-8024 respectively. This change was made in order to provide a better means for route persons to clean and service the drink merchandiser.



**Area Of Change,
Model 633 Shown
For Reference.
Part # 633-8061**

***Use Part#
485-8024 For
Combination
Merchandisers***

This change took effect with the following serial numbers:

Domestic	364-010282	Foreign	363-080203
	630-010649		365-080128
	633-015456		631-080985
	636-018147		788-080009
	637-016745		789-080074
	655-010103		
	785-010077		
	493-010259		

This change has been implemented as part of our ongoing product improvement process and is not a required update to older machines. If the current owner of a merchandiser chooses to update a machine with this improvement, it is solely at their discretion. Parts are available for purchase from the National Vendor Parts Department and any labor to install or modify any existing equipment is the owner's responsibility.

John Naughton
Service Department