



CRANE National Vendors


SERVICE BULLETIN

12955 Enterprise Way
Bridgeton, MO 63044-1200

Technical Service (800) NAT-VEND
Parts (800) NA1-PART
Sales/Parts Fax (800) 531-2580
General Information (800) 325-8811

B6339903**Universal Cup Ring Assembly****October 20, 1999**

The seven to twelve ounce cup drop ring assembly and the twelve to eighteen ounce cup drop ring assembly have been replaced by a new cup drop ring assembly, part # 633-3008.



***New Universal Cup Ring
#633-3008.
Replaces #'s 314-3005
and 314-3055***

This new cup drop ring will better facilitate the vending of styrofoam vend cups as well as provide one cup ring assembly that can be utilized to drop cups as small as five ounces or as large as twenty ounces. The new ring assembly can be discerned from the old style ring by its black color, the previous style rings were white. The new rings will also show signs of "marbling" due to a calcium strengthening agent that is added during the molding process. This discoloration does **NOT** mean the material is defective, it is normal result of this process and material. The marbling has always been present in the material, it only becomes visible when color is added to the plastic.

This change began in production with the following serial numbers.

Domestic	327-010116	636-010421
	328-010338	637-016954
	630-010668	653-010048
	633-015713	655-010138

International 631-081032

Over

This change is being implemented as part of our ongoing product enhancement process and is not a required update to older machines. If the current owner of a machine chooses to update a machine with this improvement, it is solely at their discretion. Parts are available for purchase from the National Vendor Parts Department and any labor to install or modify any existing equipment is the owner's responsibility.

John Naughton
Service Department