

Technical Bulletin

Bulletin Number: 408 Revision Number: R-03

Release Date: February 5, 1991 Revision Date: March 27, 1997

SUBJECT: CHANNEL CAPS

MODELS AFFECTED: DNCB -6 Dual Adaptables DNCB -10 Dual Adaptables
 DNCB -6 Adaptables DNCB -8 T-Models
 DNCB -6 T-Models DNCB -8 Dual Adaptable Models

SERIAL BREAK: T-Models serialized 0001-3210AP and higher have Channel Caps factory installed.
 1¼ Deeper Models 0001-2735BI and higher have Channel Caps factory installed.

REASON: To protect packages from the hem channel's edge during product loading.

ORDER:

	Kit 1 DNCB -6 Dual Adapt.	Kit 2 DNCB -6 Adapt.	Kit 3 DNCB -6 T-Model	Kit 4 DNCB -8 Dual Adapt.	Kit 5 DNCB -10 Dual Adapt.	Kit 6 DNCB -8 Dual T-Model
Channel Cap (901,805,130.11)	1	5	0	2	0	0
Channel Cap, Right (901,805,140.01)	2	1	0	2	1	0
Channel Cap, Left (901,805,150.01)	2	1	0	2	1	0
Channel Cap T (901,805,160.01)	0	0	5	0	0	1
Channel Cap T, Right (901,805,170.01)	0	0	1	0	0	2
Channel Cap T, Left (901,805,180.01)	0	0	1	0	0	2
Pop Rivet (901,100,620.01)	5	7	7	6	2	5




FIGURE 1




FIGURE 2
901,805,180.01
Left Channel Cap




FIGURE 3
901,805,170.01
Right Channel Cap